


Used for electrofusion jointing. After scraping and ensuring the pipe surface is free from dust and dirt, clean the area with separate wipes. Wipes are <98% isopropanol alcohol for New Zealand conditions that leave no residue. Data sheets are available.





Freephone: 0800 473 100 Freefax: 0800 767 190 Email: sales@upg.net.nz www.upg.nz

